ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0142, W0134, W0099	NA, 1st Crs	AIRFORCE COMPOUND
Segment No.	**Total Length (m)**	
12/C-W0142/S063229	251.99	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	101.98	77.529849	13.071819	77.530764	13.071619	M0003	DEAD END
2	150.01	77.529878	13.072084	77.531229	13.071794	M0003	W0101

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
PROVIDING IMPROVEMENTS DRAINS AT SHETTIHALLI JANATA COLONY	1500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender		012-15-000007
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/348/2014-15	31/03/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SURENDRA B T		0.00
Phone No.	**E-Mail ID**	
8836454859		

eld Inspection Details

Number of Trees	Any Other Information	Name
0		ravi
Date of Inspection	**Remarks**	
30/01/2016		

	Category	Image	Photo Remark
3	Drain Condition		Location was not determined.
4	Drain Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOWDA	30/01/2016	29/02/2016	COMPLETED
EE	JOGI SIDDEGOWDA	30/01/2016	29/02/2016	COMPLETED
AEE	JAYALINGAPPA	30/01/2016	29/02/2016	COMPLETED
AE	RAVI	30/01/2016	29/02/2016	COMPLETED
AE	RAVI	30/01/2016	29/02/2016	COMPLETED

Ravi. N.IC

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0142, W0134, W0099

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು